










System overview

Quick connection terminals with spring pressure



1- 2 pole, both sides - manual override - tool operable

Components

	5331 - Quick connection terminal 1.5mm² 1-pole gray for manual operation null	
	5332 - Screwless terminal 1.5mm² 2-pole Quick connect terminal for manual operation	
	5334 - Screwless terminal 1.5mm² 2-pole Quick-connect terminal for manual and mold actuation	
	5333 - Quick connection terminal 1.5mm² 1-pole gray for manual and tool null	